

## henri wauquiez wauquiez centurion 45 115000€ - 1993

### GENERAL

Manufacturer : henri wauquiez  
 Model : wauquiez centurion 45  
 Year : 1993  
 Material : GRP Poly  
 Length : 13.70  
 width : 4.00  
 Draft : 2.35  
 Keel : Undefined  
 Hull : Monohull  
 Weight : 11000.00  
 Lifteraft : No  
 Area : Espagne  
 Berth place available : Yes  
 Remaining leasing : No  
 Remaining payments :  
 Remaining amount :  
 Pavilion : Allemand

### FACILITIES

Nb of double cabins : 2  
 Nb of sailor cabins :  
 Bathrooms : 1  
 Toilets type : Sailor  
 Number of berths :  
 Flybridge :

### ELECTRONICS

Radar : Yes  
 Radar details :  
 Autopilot : Yes  
 Autopilot details :  
 Headings regulator : Yes  
 Depth sounder :  
 Depth sounder details :  
 GPS :  
 GPS details :  
 Plotter :  
 Plotter details :  
 Navtex :  
 VHF : Yes  
 Vane anemometer :  
 12 / 220 V converter :  
 Watermaker : Yes  
 Watermaker details :

### COMFORT

Ice maker :  
 Freezer :  
 Stove :  
 Microwave :  
 Oven :  
 Heating :  
 Hob :  
 Laundry :  
 Dishwasher :  
 TV antenna :  
 TV :  
 Radio CD :  
 Outdoor speakers :  
 DVD :  
 TV SAT antenna :

### ENGINES

Brand : perkins prima 50  
 Motor model : prima 50  
 Fuel type : Diesel  
 Mounting : In Board (IB)  
 Number of engines : 1  
 Power unit.(HP) : 50  
 Engines details :  
 Hours : 1800  
 Transmission :  
 Fuel tank : 250

### MAYOR EQUIPMENT

Bow thruster :  
 Stern thruster :  
 Marine generator : Yes  
 Marine gene. details :  
 Number of batteries :  
 Air conditioning :  
 Shore power :  
 Chargers :  
 Chargers & Air con. details :  
 Hot water :  
 Holding tank : No  
 Water tank capacity : 0  
 Flaps :  
 Anchorage :  
 Tender :  
 Engines tender : Yes  
 Engines tender details :

### BRIDGE EQUIPMENT

Gangway : No Hydraulic : No  
 Davits :  
 Aft platform :  
 Bathroom ladder :  
 Electrical windlass :  
 Sun mattress :  
 Windshield cover :  
 Winter cover :  
 Cockpit cover :  
 Sprayhood :  
 Furling genoa :  
 Spinnaker : Yes  
 Lazy bag :  
 Lazy jack :  
 Number of mast :  
 Pole : Yes  
 Second stay :  
 Teak deck :  
 Teak cockpit :

### DIVERS

Curative osmosis treatment : No Year :  
 Preventive osmosis treatment : No Year :  
 Comments :